

Filtex FX600 Dust Extractor with Explosion Relief Panel - 9.2kW / 12.3Hp



Stock No	EE2242
Manufacturer	Filtex
Model	FX600
Year of Manufacture	c.1994
Serial	7092
Condition	From a working environment, Excellent Condition
Approx Duty CFM / M ³ /Hr	2400 - 4800 // 4085 - 8165
Filter Area ft ² / m ²	600 // 55.74m ²
Other Info	ABB Motor. Explosion relief panel.
Location	Our Central Warehouse, Aldridge, UK
Weight (kgs)	750
External Dimensions (WxDxH mm)	1890 x 1110 x 3150mm

Description

This preowned FX600 F dust extractor delivers powerful and reliable performance with its 9.2kW / 12.3Hp motor, making it ideal for managing a wide range of fine dust applications. Versatile, efficient and built for safety, it also features an explosion relief panel.

The FX600 is a fully self contained free standing, high efficiency, dust reduction and elimination extractor complete with fully automatic electrical shaking mechanism.



This dust abatement machine features a large dust holding capacity with twin dust collection buckets.

The body incorporates individual access doors with quick release fasteners for ease of inspection of the filter bags and fan.

Suitable for dry dust environments such as carpentry shops, engineering, cement works, paper mills and gypsum works to name but a few.

The unit incorporates a 9.2kW // 12.3hp fan, motor and dual filter assemblies with mechanically operated shaking mechanism, designed to accept combinations of filter cloths to meet varying applications in industry.

Features Include

- Full width hinged access doors, with quick release fasteners, provide easy inspection or removal of fan, motor or either filters sets.
- 9.2kW // 12.3Hp high performance fan set.
- Explosion relief panel.
- Automatic electrical shaking mechanism control unit consists of contactors and time delay relays, so that when the stop button is operated, the fan motor is allowed to run down before the shaker motor is automatically energised. This then runs for a pre-determined period, after which the whole system is shut down and resets.

Photographs taken prior refurbishment. Our refurbishment service is not available on all machines.