

## Donaldson Torit (DCE) UMA Unimaster 102 K3 Dust Extractor



Stock No	<a href="#">EE2265</a>
Manufacturer	<a href="#">Donaldson Torit (DCE)</a>
Model	102 K3
Year of Manufacture	1996
Serial	637285
Condition	From a working environment, Good Condition, Current Model
Approx Duty CFM / M <sup>3</sup> /Hr	600/1000
Filter Area ft <sup>2</sup> / m <sup>2</sup>	100/10
Other Info	Autoshaker Controller
Location	Our Central Warehouse, Aldridge, UK
Weight (kgs)	265
External Dimensions (WxDxH mm)	960 x 675 x 2400mm

### Description

This pre owned Unimaster 102 K3 dust collector from Donaldson Torit is designed to maximize dust collection and the life of the collector components for years of extended service, the Unimaster collector's compact design and quiet operation provides efficient, trouble-free service.

- A self-contained collector with everything needed to begin collecting dust, the Unimaster comes complete with fan and fan motor, automatic shaker and shaker motor, and system controller making installation quick and easy.



Since the automatic shaker cleans the bag filters, there is no need for expensive compressed air. Ideal for intermittent operations in plant processes, the Unimaster can be used as a central system or at the point of dust generation.

### Design features

- Compact Design, minimises floor space and fits in virtually any plant layout.
- Versatility, will suit a variety of dust collection applications
- Quiet & Efficient Operation, motors and fan are enclosed in collector housing to minimize noise.
- Easy Maintenance.
- 2ft<sup>3</sup> collection bucket.
- Quick-Release Lever allows for easy removal and maintenance of bin.
- Powerful 1.1kw // 1.5 Hp fan set
- Inlet Deflector knocks down larger particles into the hopper reducing bag abrasion and increasing bag filter life.
- Heavy-duty flexible metal inner bag coils inserted into filter bags keeps bags open to maximize airflow and assist in knocking dust off during cleaning cycle.
- Bag-Release Screws allow for easy removal of bags.

**Photographs taken prior refurbishment. Our refurbishment service is not available on all machines.**