The Marketplace for Surface Technology. New and Used Process Equipment & Machinery.

Machine Datasheet



JLS (Redditch) Ltd Double Door, Heavy Duty, 550°C Electric Heat Treatments Oven



Stock No OE2635

Manufacturer JLS (Redditch) Ltd

Model Forced Air Circulation Box Oven

Year of Manufacture 2000 Serial 00 / 4669

Condition From a working environment, Excellent Condition

Internal Size (WxDxH mm) 1000 x 1200 x 1000mm

Max Temp 550° C

Location Our Central Warehouse, Aldridge, UK

Weight (kgs) 2100

External Dimensions (WxDxH mm) 3140 x 1600 x 2450mm

Description

JLS Double Door Electric Treatments and Curing Oven, equipped with a powerful high volume low pressure air recirculation fan for horizonal air flow. This model is intended to provide rapid heating with high thermal transfer to the chamber contents and high uniformity within the chamber.

Dimensions

Internal dimension: 1000 x 1200 x 1000mm
External Dimensions: 3140 x 1600 x 2450mm





Registered in England no. 1965748

The Marketplace for Surface Technology. New and Used Process Equipment & Machinery.

Machine Datasheet



• Double doors (width x height): 1000mm x 1850mm each

Heavy Duty Applications:

- Composites
- Aluminum aging
- High temp coatings
- Heat treating
- · And other demanding high uniformity applications

Standard Features

- Maximum operating temperature: 550°C
- 304 stainless steel chamber.
- Ø660mm air circulation fan driven by a 2.2kW motor.
- Low thermal mass insulation.
- Eurotherm 2216L proportional digital programmable temperature.
- Eurotherm 2216L over temperature controller.
- Thyristor fired electric heating: 36 kW
- Fitted with 24 x 1460 Watt mineral insulated sheathed heating elements.
- Total power: 36kW
- Traditional rugged design of robust construction.
- Air-circulation using horizontal axial fan.
- Heating deactivated if doors are opened.
- Generous insulation.
- Temperature range: 100-550°C
- 415Volts, 3phase, 50 Hz
- Exceptional temperature uniformity throughout the working chamber.

Photographs taken prior refurbishment. Our refurbishment service is not available on all machines.



